

TEST REPORT

No. : XMIN2112013230ML

Date : Dec 22, 2021



Page: 1 of 3

CUSTOMER NAME:	RAJA INTERNATIONAL GENERAL TRADING FZE
ADDRESS:	A2-89, SAIF ZONE, SHARJAH, UNITED ARAB EMIRATES

ISU DRILL PIPE CASING TOOL 1500MM Sample Name :

Material and Mark Plastic and fiberglass :

Other Information **ISU-DCT-15M** :

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

Date of Receipt	:	Dec 06, 2021
Testing Start Date	:	Dec 06, 2021
Testing End Date	:	Dec 22, 2021
Test result(s)	:	For further details, please refer to the following page(s) (Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for SGS-CSTC Standards Technical Services Co., Ltd Xiamen Branch **Testing Center**

Spik

Spike Tang Authorized signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>http://www.sgs.com/en/Terms-and-Conditions.aspx</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>http://www.sgs.com/en/Terms-and-Conditions.aspx</u> and, for electronic format documents, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document as dvised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document. Sont document taents the approximation of biggitons under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. report & certificate. testing / ne:(86-755) 8307 n:To check the please cont

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China. 361101 t (86-592) 5761588 中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编:361101 t (86-592) 5761588

www.sgsgroup.com.cn e sgs.china@sgs.com

f (86-592) 5765380

f (86-592) 5765380



TEST REPORT

No. : XMIN2112013230ML Date : Dec 22, 2021 Page: 2 of 3

Pull test:


Test method: according to the client's requirements, fixed the sample on the test machine. Apply the pull force as a rate of 5mm/min till the force reaches 1650N, then hold the force for 5 min if the sample without obvious deformation. Observe whether the sample was damage after the test. Push test:

Test method: according to the client's requirements, fixed the sample on the test machine. Apply the push force as a rate of 5mm/min till the force reaches 2800N, then hold the force for 5 min if the sample without obvious deformation. Observe whether the sample was damage after the test.

Test	Result:
1000	rtcount.

Test Item	Test Result
Pull test	When the force reached 1650N the sample was not damaged
Push test	When the force reached 2800N the sample was not damaged.

Test curve:





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.format-opocument.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document. This document contained of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report feer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN-Doccheck@asg.com

No.31 Xianghong Road, XiangAn Torch Industrial Zone, Xiamen, Fujian Province, China. 361101 t (86-592) 5761588 f (86-592) 5765380 www.sgsgroup.com.cn 中国・福建・厦门・火炬 (拥安) 产业区期虹路31号 邮编:361101 t (86-592) 5761588 f (86-592) 5765380 e sgs.china@sgs.com



TEST REPORT

No. : XMIN2112013230ML Date : Dec 22, 2021 Page: 3 of 3

Sample Photo:



******** End of report*******



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.agpx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.agpx and, for electronic format documents, attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not excense the aptroval of the Company's old responsibility is to its Client and this document. This document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN-Doccheck@gs.com

No.31 Xianghong Road, Xiang/An Torch Industrial Zone, Xiamen, Fujian Province, China. 361101 t (86-592) 5761588 f (86-592) 5765380 中国•福建•厦门•火炬(期安)产业区期虹路31号 邮编:361101 t (86-592) 5761588 f (86-592) 5765380

www.sgsgroup.com.cn

e sgs.china@sgs.com